

# Asbestos & Hazardous Materials Survey

## AMP Capital



700 Bourke Street  
Docklands VIC 3000

December 2020

## Asbestos & Hazardous Materials Survey

<b>Report For</b>	AMP Capital
<b>Address</b>	700 Bourke Street, Docklands VIC
<b>Site Inspection By</b>	Matthew Hyde, Senior Consultant
<b>Date of Inspection</b>	30 November 2020
<b>Conferred With</b>	Darren Hynes, Facilities Supervisor, AMP Capital

### Disclaimer & Statement of Confidentiality

This document has been prepared solely for the benefit of the Client for the purpose set out herein and should not be used for any other purpose than as an expression of the opinion of RiskTech Compliance (Jaromowo Pty Ltd - ABN 31 610 492 423) and the other related matters dealt with herein. The client may provide information contained in this report to the landlord, its tenants and consultants.

No responsibility is accepted to any other party for any loss or damage resulting from the use by the Client of this document for any reason whatsoever including but not limited to negligence on the part of RiskTech Compliance (RTC) or even a breach by RTC in its contractual obligation to the Client in preparing the document. This document is confidential to the Client and RTC does not intend that any other person accept or rely upon it.

The Document is based on RTC's analytical processes and the information provided to RTC by the Client and/or nominated third parties at the time of provision of information both on location and/or in written format. Such information supplied has not been independently verified by RTC. Whilst this document is accurate to the best of RTC's knowledge, information and belief, RTC cannot guarantee the completeness or accuracy of any descriptions or conclusions based on the supplied information.

The information or recommendations contained in this document are advisory only and RTC has no responsibility for the management or operation of any financial and/or risk minimisation and/or related procedures which may be implemented.

Documents may be prepared by specialists sub-contracted by RTC on an "as needed" basis to match assignments.

During the course of normal site works care should be exercised when entering any previously inaccessible areas and it is important to cease work pending further sampling if materials suspected of containing asbestos or other hazardous materials are present. Therefore prior to refurbishment or demolition works, further investigations and assessment is required to ensure materials that may be in previously inaccessible areas or areas not fully inspected.

### Document Revision Record

File Name	Prepared By	Reviewed By	Issue Date	Issue No.
AMP Hazmat 700 Bourke Street Docklands VIC Dec20	Matthew Hyde Senior Consultant	Bernard Day General Manager	3/12/20	1

# Contents

---

1.	Executive Summary	4
2.	Introduction	5
2.1	Site Description	5
2.2	Scope of Works	6
2.3	Risk Assessment	7
2.4	Priority Rating System for Control Recommendations	7
2.5	Documentation History	8
2.6	Limitations & Areas Not Accessed	9
3.	Findings	10
3.1	Asbestos	10
3.2	Synthetic Mineral Fibre (SMF)	11
3.3	Polychlorinated Biphenyls (PCBs)	13
3.4	Lead Paint	13
4.	Recommendations	14
4.1	Priority Recommendations	14
4.2	Management Recommendations	14
4.3	Refurbishment Recommendations	14
Appendix 1	Asbestos / Hazardous Materials Register	15
Appendix 2	Laboratory Sample Results	21

# 1. Executive Summary

## Scope

RiskTech Compliance were engaged by AMP Capital to undertake an Asbestos and Hazardous Materials Survey of the property located at 700 Bourke Street, Docklands VIC to assess the possible presence of Asbestos and Hazardous Materials used in the construction of the buildings on site.

The survey process encompassed an inspection of accessible areas of the buildings in accordance with *VIC Occupational Health and Safety Regulations, 2017* and the *Managing Asbestos in the Workplace: Compliance Code (WorkSafe Victoria, 2019)*.

This report documents RiskTech Compliance's survey findings as per this scope. This is a non-destructive assessment for occupational purposes, not for major refurbishment or demolition. Hazardous materials assessed include asbestos containing materials (ACM), synthetic mineral fibre (SMF), polychlorinated biphenyls (PCBs) and lead-based paint.

The site was operational at the time of the inspection and it should be noted that only the accessible areas of the buildings on the site were assessed.

## Findings

The table below summarises the identified hazardous materials on site:

Hazardous Material	Details	Risk Status
Asbestos	Nil	-
SMF	Pipework insulation – Level 15 Boiler Room, Ceiling Space of Office Levels 1-14; Rigid Ductwork Insulation - Ceiling Space of Office Levels 1-14; Flexible Ductwork Insulation - Ceiling Space of Office Levels 1-14; Internal insulation to hot water units – Level 15 Plant Room & Office Levels 1-14; Fire stopping insulation - Electrical and Communications Cupboards on Office Levels 1-8.	Low
PCBs	Nil	-
Lead Paint	Nil	-

## Recommendations

### Priority Recommendations

- Nil

### Management Recommendations

- No asbestos materials were identified on site therefore an Asbestos Management Plan is not required to be developed for the site.
- Maintain identified SMF containing materials in good condition. Remove under controlled conditions prior to demolition/refurbishment.

### Refurbishment/Demolition Recommendations

- Nil.


## 2. Introduction

RiskTech Compliance were engaged by AMP to undertake an Asbestos and Hazardous Materials Survey of the property located at 700 Bourke Street, Docklands VIC to assess the possible presence of Asbestos and Hazardous Materials used in the construction of the buildings on site.

The site was operational at the time of the inspection and it should be noted that only the accessible areas of the buildings on site were assessed.

### 2.1 Site Description

<b>Site Address</b>	700 Bourke Street, Docklands VIC3000
<b>Construction Date</b>	2013
<b>Current Use</b>	Commercial
<b>General Description</b>	Level 15 – Plant Rooms Levels 1-14 Offices Ground and Mezzanine – NAB Branch & Cafe P1 and P2 – Basement Level Parking, Loading Dock and Plant Rooms



**Site Location:** 700 Bourke Street, Docklands VIC

Image courtesy Google Maps 2020



## 2.2 Scope of Works

The survey process encompassed an inspection of the exterior and interior areas including plant rooms of the buildings on site. This report documents RiskTech's survey findings as per this scope.

The survey was undertaken in accordance with:

- VIC Occupational Health and Safety Regulations, 2017;
- *Managing Asbestos in the Workplace: Compliance Code* (WorkSafe Victoria, 2019).

The scope included an Asbestos and Hazardous Building Materials survey of the building on site, with express intent to identify the presence of the following:

- Asbestos Containing Materials (ACM);
- Synthetic Mineral Fibres (SMF);
- Polychlorinated Biphenyls (PCBs); &
- Lead Paint.

The survey involved:

- Discussions with relevant personnel and review of historical aerial photographs to ascertain the building age and history.
- Review of relevant documentation including previous audit reports and abatement records where present.
- A visual inspection of accessible and representative structural elements and construction materials of the buildings to identify hazardous materials.
- Detailed sampling and identification of suspected asbestos materials. Small representative samples of suspected asbestos-containing material were collected in plastic bags with clip-lock seals.
  - 3 samples were collected and subsequently analysed in an external NATA-accredited laboratory (Envirolab Services Pty Ltd) for the presence of asbestos by Polarised Light Microscopy.
  - Refer to **Appendix 2** for laboratory results.
- Sampling of suspected lead paint materials. The objective of lead paint identification in this survey is to highlight the presence of lead-based paints within the buildings, not to specifically identify every source of lead-based paint.
  - No paint chip samples were collected during the current survey.
- During the inspection, details of the capacitors were noted and assessed against a list of known PCB-containing capacitors: *Identification of PCB-Containing Capacitors – Australian & New Zealand Environment and Conservation Council (ANZECC) 1997*. Access to the capacitors within insitu light fittings was not available at the time of the audit, as a qualified electrician was not present to access the fittings. An assessment on the likelihood of light fittings containing PCB capacitors has been made in lieu of a visual inspection, based on the apparent age and style of the light fittings.
- Identification of SMF materials was undertaken by visual assessment.
- Preparation of this report, including findings, recommendations, an Asbestos & Hazardous Materials Register, photographs & laboratory results.

A strategy of using representative samples of suspected hazardous materials has been used to minimise the number of samples and degree of disturbance. Because of this strategy, findings of the audit should be interpreted such that all visually similar materials in the same vicinity must be assumed to be composed of the same material until proven otherwise. Where these factors have indicated that there is a possibility of exposure to airborne asbestos fibres or other hazardous material, appropriate risk control measures are recommended.

The quantities presented in the Asbestos & Hazardous Materials Registers are indicative estimates only and should not be used as absolute quantities for tendering purposes to cost removal / remediation. Furthermore, further intrusive investigations and testing should be undertaken prior to planned redevelopment works in order to ascertain the full extent and quantities of hazardous materials and also to engage a professional quantity surveyor organisation if quantities are to be relied upon.

The scope of works did not include sub-surface investigations for asbestos / hazardous materials or identification of any asbestos / hazardous materials containing underground services such as telecommunication and electrical conduits, stormwater, sewer and drinking water pipework and service pits or similar materials.

## 2.3 Risk Assessment

To assess the health risk posed by the presence of ACM, all relevant factors must be considered. These factors include:

- Evidence of physical damage
- Proximity of air plenums and direct air stream
- Friability of the material
- Requirement for access for building/maintenance operations
- Likelihood of disturbance of the asbestos material
- Accessibility
- Exposed surface areas
- Environmental conditions

These aspects are in turn judged upon (i) potential for fibre generation, and (ii) the potential for exposure. Where these factors have indicated that there is a possibility of exposure to airborne fibres, appropriate recommendations for repair, maintenance or abatement of the ACM are made.

The risk factors described above are used to rank the health risk posed by the presence of asbestos-containing materials.

- A *low* risk ranking describes asbestos materials that pose a low health risk to personnel, employees and the general public providing they stay in a stable condition.
- A *medium* risk ranking applies to materials that pose an increased risk to people in the area.
- Asbestos materials that possess a *high*-risk ranking pose a high risk to personnel or the public in the area of the material.

## 2.4 Priority Rating System for Control Recommendations

The following priority rating is adopted to assist in managing the ACM identified on the site.

A P1 (high priority) to P4 (low priority) rating system is employed:

- P1** – Immediate remedial works are required
- P2** – Remedial works are required within 3-6 months
- P3** – Remedial works are generally not required, but where required, these works should be undertaken within a planned control program
- P4** – No remedial works are required

## 2.5 Documentation History

Access to the site and discussions were held with Darren Hynes, Facilities Manager of AMP. The site was only partially occupied at the time of the assessment, due to COVID-19 restrictions with the existing tenant operating with minimal staff or having temporarily vacated.

The following documentation was reviewed as part of this assessment:

- An Asbestos & Hazardous Materials Audit was conducted of the site prior to the construction of the building dated November 2010, developed by Noel Arnold & Associates (Ref: MC0666:86258). A total of 5 samples were taken during this assessment of which 1 returned a positive result for asbestos.

This report identified/suspected the following asbestos containing materials on site:

- Cement sheet debris fragments in the car park area under the bridge.

It is assumed the asbestos material was removed prior to the construction of the current building in 2013.



## 2.6 Limitations & Areas Not Accessed

This is a non-destructive assessment for occupational purposes. It is not to be used for any major refurbishment or demolition, where a more invasive destructive survey would be undertaken in line with plans for re-development.

In accordance with the *VIC Occupational Health and Safety Regulations 2017*; and, *Managing Asbestos in the Workplace: Compliance Code* (WorkSafe Victoria, 2019), inaccessible areas that are likely to contain asbestos must be presumed as containing asbestos material until further inspection and analysis of samples has been undertaken by an approved analyst.

Typical areas likely to be deemed inaccessible under this regulation are:

- Height restricted areas e.g. Inaccessible ceiling/roof spaces and facade;
- Inaccessible sub-floor spaces/tunnels;
- Under carpet/vinyl or other floor coverings;
- Above set ceilings;
- Service shafts, risers, ducts etc. concealed within building structure;
- Lift shaft, landing doors and lift cabin fittings and doors;
- Areas accessible only by dismantling equipment or performing localised demolition works;
- Concealed and inaccessible areas such voids and cavities within building structure, which are only accessible during major demolition works;
- Concealed behind other materials and linings;
- Building façade fixing brackets;
- Wall cavities/partitions;
- Behind ceramic wall and floor tiles;
- Inside mechanical equipment e.g. within air conditioning re-heat boxes;
- Gaskets & sealants to pipework, ductwork, mechanical equipment, window glazing & construction joints;
- Waterproof membranes;
- Sealed fire doors; &
- Within live electrical switchboards.

It should be noted that the presence of residual asbestos material on plant items (e.g. boilers) or behind wall, ceiling and floor linings cannot be ascertained without extensive removal and impact to the linings, fittings and services.

Other specific areas not accessed during the survey include:

- Various Tenant Levels (Levels 14, 12, 10, 8 & 6) were inspected, ; &
- Upper roof area (outside walkways);

As the survey assessment is focused on reasonable accessible areas, it is possible that asbestos / hazardous materials may not be identified without further investigations, demolition or damage to building structures and associated finishing materials, fixtures and fittings, isolation and dismantling of disused and/or operation plant and equipment and also work, health and safety considerations (eg; heights & live equipment).

As sampling of suspected asbestos / hazardous materials is only representative, it is possible that asbestos may not be detected in the sample collected due to factors such as non-homogeneity of asbestos within the material and also the sensitivity and constraints of the analytical method.

## 3. Findings

### 3.1 Asbestos

#### 3.1.1 Summary of Findings

The following friable ACMs were identified or suspected on site.

Asbestos Material	Location	Risk Status	Extent
Nil	-	-	-

The following non-friable ACMs were identified or suspected on site.

Asbestos Material	Location	Risk Status	Extent
Nil	-	-	-

#### 3.1.2 Discussion

No asbestos materials were identified on site therefore an Asbestos Management Plan is not required to be developed for the site.


#### 3.1.3 Photographs – Non-Asbestos Items Sampled



**Photo 1:** Level 15, Plant Room, Boiler Room, Motor to Boiler – Non-asbestos containing gaskets



**Photo 2:** Level 15, Plant Room, Boiler Room, Pipework to Boiler – Non-asbestos containing gaskets



**Photo 3:** Level 15, Plant Room, Ductwork, Sprayed Insulation – Non-asbestos insulation material

## 3.2 Synthetic Mineral Fibre (SMF)

### 3.2.1 Background Information

Synthetic Mineral Fibre (SMF) is a man-made insulation material used extensively in industrial, commercial and residential sites as fire rating, reinforcement in construction materials and as acoustic and thermal insulators. Types of SMF materials include fibreglass, rockwool, ceramic fibres and continuous glass filaments.

There are two basic forms of SMF insulation, bonded and un-bonded. Bonded SMF is where adhesives, binders or cements have been applied to the SMF before delivery and the SMF product has a specific shape. Un-bonded SMF has no adhesives, binders or cements and the SMF is loose material packed into a package.

### 3.2.2 Summary of Findings

The following SMF materials were identified/suspected on site:

SMF Item	Location/Comments
Pipework insulation	Level 15, Plant Room - Boiler Room, Ceiling Space of Office Levels 1-14
Rigid Ductwork Insulation	Ceiling Space of Office Levels 1-14
Flexible Ductwork Insulation	Ceiling Space of Office Levels 1-14
Boiler insulation	Level 15, Plant Room - Boiler room
Internal insulation to hot water units	Level 15, Plant Room
Fire stopping insulation	Electrical and Communications Cupboards on Office Levels 1-14 Level P1 Main Switch Room

The SMF materials identified on site were generally in a good condition and installed to industry standards.

### 3.2.3 Photographs – SMF




**Photo 4:** Roof Level, Boiler Room – SMF to pipework insulation



**Photo 5:** Roof Level, Boiler Room – SMF to internal areas of boiler



**Photo 6:** Level 15, Plant Room– SMF internal insulation to hot water units



**Photo 7:** Office Levels, Electrical and Communications Cupboards – Fire stopping insulation to floor/ceiling penetrations



**Photo 8:** Office Levels, Kitchenettes– SMF internal insulation to hot water units



**Photo 9:** Office Levels, Ceiling Space– SMF to flexible ductwork insulation



### 3.3 Polychlorinated Biphenyls (PCBs)

#### 3.3.1 Background Information

The major use of PCBs in the electrical industry has been as an insulating fluid inside transformers and capacitors. Capacitors containing PCBs were installed in various types of equipment including fluorescent light fittings during the 1950's, 60's and 70's.

#### 3.3.2 Summary of Findings

No PCB containing capacitors were identified during the current Hazardous Materials Survey. As the building was constructed in 2013, fluorescent light fittings are unlikely to contain PCBs as they were phased out in the late 1970's.

PCB-Containing Item	Location/Comments	Extent
Nil	-	-

### 3.4 Lead Paint

#### 3.4.1 Background Information

In December 2017, Standards Australia has adopted a significantly lower lead content limit from 1% to 0.1% for the definition of lead paint.

Lead paint, as defined by the Australian/New Zealand Standard AS/NZS 4361.2: 2017 *Guide to hazardous paint management; Part 2: Lead paint in residential, public and commercial buildings* is "a paint film that contains greater than 0.1% lead by mass in the dry film."

Paint with lead pigment was manufactured up until the late 1960's, and in 1969 the National Health and Medical Research Council's Uniform Paint Standard was amended to restrict lead content in domestic paint. Paint manufactured for non-industrial use since 1970's contain less than 1% lead. However, it is possible that industrial paints containing a higher lead concentration may have been applied to residential, public and commercial buildings.

Since 1997, paints have been manufactured with less than 0.1% lead by mass and this limit has been adopted by Standards Australia for the definition of lead-containing paint.

#### 3.4.2 Summary of Findings

As the building was constructed in 2013 lead paint systems are unlikely to contain lead paint.

No lead paint systems were identified on site.

## 4. Recommendations

### 4.1 Priority Recommendations

- Nil

### 4.2 Management Recommendations

- No asbestos materials were identified on site therefore an Asbestos Management Plan is not required to be developed for the site.
- Maintain identified SMF containing materials in good condition. Remove under controlled conditions prior to demolition/refurbishment.

### 4.3 Refurbishment Recommendations

- Nil



# Appendix 1 Asbestos / Hazardous Materials Register

## Example Asbestos Register

The Asbestos Register on the following pages contains a detailed description and risk assessment information. This is outlined below:

Each asbestos item's location and description is included in the first column

The sample number corresponds to the Laboratory report (if samples taken) in [Appendix 2](#)

Photos of selected items are included in the [Section 3 Findings](#)

An estimated amount of the asbestos materials is outlined here

Based on the risk assessment, the control priority is included here as a guide:

P1

 – Immediate remedial works are required

P2

 – Remedial works are required within 3-6 months

P3

 – Remedial works are generally not required, but where required, these works should be undertaken within a planned control program

P4

 – No remedial works are required

Location Item Description Comments	Sample No.	Sample Status	Photo No.	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Labelled ?	Control Priority	Control Recommendation
Ground Floor												
Ground Floor Lobby, Western Wall Fibre cement sheeting	A01	Positive	1	5m <sup>2</sup>	Good	Non Friable	Low	Low	2018	No	P4	Label and maintain item in good condition. Remove by a Class A/B licensed asbestos contractor prior to renovations.
Switch Room Electrical cabinet – electrical backing board *Not sampled due to live equipment	_*	Suspected Positive	2	1 units	Good	Non Friable	Low	Low	2018	Yes	P4	Maintain in good condition and remove by a Class A/B asbestos contractor prior to renovations.

Sample Status identifies if the material contains asbestos:

- Positive:** the sample contains asbestos (refer to the analysis report in [Appendix 2](#))
- Negative:** the sample does not contain asbestos.
- Where the material was not sampled, but is similar to another sample, the sample status is **Assumed Negative** or **Assumed Positive**.
- Based on knowledge, an item may be **Suspected Positive** or **Suspected Negative** if the material was inaccessible at the time of inspection

These columns outline the risk assessment of each ACM:

- Condition:** Good, Fair or Poor
- Friability:** Friable or Non-friable
- Disturbance Potential:** Low, Med or High depending on a number of factors such as access requirements, airflow etc
- Risk Status:** describes the overall health risk posed by the ACM (Low, Med or High)

A date for re-inspection is given based upon the risk assessment

Do the materials have asbestos warning labels?

Recommended control measures are included for identified ACM

## Asbestos Register

Site Address: 700 Bourke Street, Docklands VIC								Assessed By: Matthew Hyde Senior Consultants (RiskTech Compliance) Date: 30 November 2020				
Location Item Description Comments	Sample No.	Sample Status	Photo No.	Extent	Condition	Friability	Disturb. Potential	Risk Status	Re-inspect Date	Labelled?	Control Priority	Control Recommendations
<b>Roof Level</b>												
Façade, Upper Levels No access to upper sections of façade	-	-	-	-	-	-	-	-	-	-	-	Further inspection required to the façade when access is made available.
Exterior Roof Level, Throughout No asbestos materials identified	-	-	-	-	-	-	-	-	-	-	-	-
<b>Level 15 Plant Room</b>												
Boiler Room Motor to Boiler - Gasket	RTC2020-A01	Negative	1	-	-	-	-	-	-	-	-	-
Boiler Room Pipework - Gasket	RTC2020-A02	Negative	2	-	-	-	-	-	-	-	-	-
Generator Room Pipework & Manifold – Gaskets *not sampled due to manufacture date 2012	_*	Suspected Negative	-	-	-	-	-	-	-	-	-	-
Various Locations Ductwork – Sprayed insulation	RTC2020-A03	Negative	3	-	-	-	-	-	-	-	-	-
Plant Room Electrical Distribution Boards No asbestos materials identified	-	-	-	-	-	-	-	-	-	-	-	-
Fire Stairwell & Plant Room Fire Doors (Tagged RE Spence, 2012) - Core Insulation *Not sampled due to age of manufacture	-	Suspected Negative	-	-	-	-	-	-	-	-	-	-

# Asbestos & Hazardous Materials Survey

700 Bourke Street, Docklands VIC

Location Item Description Comments	Sample No.	Sample Status	Photo No.	Extent	Condition	Friability	Disturb. Potential	Risk Status	Re-inspect Date	Labelled?	Control Priority	Control Recommendations
<b>Levels 1-14</b>												
Fire Stairwell & Plant Room Fire Doors (Tagged RE Spence, 2012) - Core Insulation *Not sampled due to age of manufacture	-	Suspected Negative	-	-	-	-	-	-	-	-	-	-
Electrical Cupboards Electrical Distribution Boards No asbestos materials identified	-	-	-	-	-	-	-	-	-	-	-	-
Offices, toilets, hallways, plant rooms, lift lobby areas, ceiling space No asbestos materials identified	-	-	-	-	-	-	-	-	-	-	-	-
<b>Levels P1 &amp; P2</b>												
Fire Stairwell & Plant Room Fire Doors (Tagged RE Spence, 2012) - Core Insulation *Not sampled due to age of manufacture	-	Suspected Negative	-	-	-	-	-	-	-	-	-	-
Main Switch Room Electrical Distribution Boards No asbestos materials identified	-	-	-	-	-	-	-	-	-	-	-	-
Offices, toilets, hallways, plant rooms, lift lobby areas, car park, loading dock No asbestos materials identified	-	-	-	-	-	-	-	-	-	-	-	-

## Other Hazardous Materials

### Synthetic Mineral Fibres (SMF) Register

Location Item Description	Photo No.	Form	Extent	Condition	Risk Status	Control Recommendations
<b>Roof Level</b>						
No SMF materials identified	-	-	-	-	-	-
<b>Level 15 Plant Room</b>						
Boiler Plant Room Hot Water Pipework - Insulation	4	Bonded	~40 m	Good	Low	Maintain in good condition. Remove under controlled conditions prior to demolition/refurbishments.
Boiler Room, Boiler - Insulation	5	Bonded	2 units	Good	Low	Maintain in good condition. Remove under controlled conditions prior to demolition/refurbishments.
Plant Room Adjacent Potable Water Tank Internal Insulation to Hot Water Units	6	Bonded	~6 units	Good	Low	Maintain in good condition. Remove under controlled conditions prior to demolition/refurbishments.
<b>Office Levels 1-14</b>						
Electrical/Communications Rooms Fire Stopping Insulation	7	Bonded	~40m <sup>2</sup>	Good	Low	Maintain in good condition. Remove under controlled conditions prior to demolition/refurbishments.
Kitchens Internal Insulation to Hot Water Units	8	Bonded	~14 units	Good	Low	Maintain in good condition. Remove under controlled conditions prior to demolition/refurbishments.
Ceiling Space Rigid Ductwork Insulation	-	Bonded	~800 m	Good	Low	Maintain in good condition. Remove under controlled conditions prior to demolition/refurbishments.
Ceiling Space Flexible Ductwork Insulation	9	Bonded	~800 m	Good	Low	Maintain in good condition. Remove under controlled conditions prior to demolition/refurbishments.
Ceiling Space Pipework Insulation	-	Bonded	~1000 m	Good	Low	Maintain in good condition. Remove under controlled conditions prior to demolition/refurbishments.
<b>Levels P1 &amp; P2</b>						
Main Switch Room Fire Stopping Insulation	-	Bonded	2 m <sup>2</sup>	Good	Low	Maintain in good condition. Remove under controlled conditions prior to demolition/refurbishments.

## Polychlorinated Biphenyls (PCBs) Register

Location Item Description	Photo No.	Capacitor Specifications	No. Fittings	PCB Containing?	Control Recommendations
<b>Roof Level</b>					
Fluorescent Light Fittings Newer Appearance	-	-	-	Suspected Negative	As the building was constructed in 2013, fluorescent light fittings are unlikely to contain PCBs as they were phased out in the late 1970's
<b>Level 15 Plant Room</b>					
Fluorescent Light Fittings Newer Appearance	-	-	-	Suspected Negative	As the building was constructed in 2013, fluorescent light fittings are unlikely to contain PCBs as they were phased out in the late 1970's
<b>Levels 1-14</b>					
Fluorescent Light Fittings Newer Appearance	-	-	-	Suspected Negative	As the building was constructed in 2013, fluorescent light fittings are unlikely to contain PCBs as they were phased out in the late 1970's
<b>Levels P1 &amp; P2</b>					
Fluorescent Light Fittings Newer Appearance	-	-	-	Suspected Negative	As the building was constructed in 2013, fluorescent light fittings are unlikely to contain PCBs as they were phased out in the late 1970's

## Lead Paint Register

Location Item Description	Photo No.	Sample No.	Lead Content %	Lead Paint?	Extent	Condition	Control Recommendations
<b>Roof Level</b>							
No lead paint materials were identified	-	-	-	-	-	-	-
<b>Level 15 Plant Room</b>							
No lead paint materials were identified	-	-	-	-	-	-	-
<b>Levels 1-14</b>							
No lead paint materials were identified	-	-	-	-	-	-	-
<b>Levels P1 &amp; P2</b>							
No lead paint materials were identified	-	-	-	-	-	-	-

Note: Australian Standard "AS4361.2: 2017 *Guide to Hazardous Paint Management; Part 2: Lead Paint in Residential Public and Commercial Buildings*", is that which contains in excess of 0.1% lead by weight.



## Appendix 2      Laboratory Sample Results

---

10 December 2020

**Attention:** Matthew Hyde  
**Company:** RiskTech Compliance  
**Fax/email:** mhyde@risktech.com.au  
**Address:** Level 5, 3 Rider Boulevard, Rhodes NSW 2138  
**Client Reference:** 700 Bourke Street, Docklands VIC



Accredited for compliance  
with ISO/IEC 17025 - Testing

**SWE Report Reference:** S109316.35  
**Date of Receipt:** 08 December 2020  
**Sample Analysis Date:** 09 December 2020  
**SWE Laboratory:** Suite 25, 103 Majors Bay Road, Concord NSW 2137

**NATA Accreditation No:** 17092

**Site Number:** 18665

### Asbestos Identification

**1. Introduction:** This report presents the results of 3 samples, forwarded by RiskTech Compliance on 08 December 2020 and analysed as received for the presence of asbestos. The collection of samples for analysis is not covered under the laboratory NATA Accreditation. The sampling reference location is not verified by Safe Work and Environments (SWE).

**2. Methods:** Samples are examined under a Stereo Microscope and selected fibres are analysed via Polarized Light Microscopy in conjunction with Dispersion Staining; in accordance with Australian Standard AS4964-2004 and SWE's In-House *ALM-Method 3 - Fibre Identification*.

### 3. Results:

SWE REF.	CLIENT REFERENCE	SAMPLE DESCRIPTION	ANALYTICAL RESULTS
S109316.35/A 01	RTC2020-A01	White gasket material 0.35 g	No Asbestos Detected Synthetic Mineral Fibre Detected Organic Fibre Detected
S109316.35/A 02	RTC2020-A02	Red gasket material 0.24 g	No Asbestos Detected Organic Fibre Detected
S109316.35/A 03	RTC2020-A03	Beige insulation material 6.17 g	No Asbestos Detected Organic Fibre Detected

**Analysed and reported by:**



**Vince Nguyen**  
Analyst



**Rune Knoph**  
Approved Issuer of Report

S109316.35-FID-101220

# CHAIN OF CUSTODY - Client



**SAFE WORK & ENVIRONMENTS**  
ENVIRONMENTAL & WHS CONSULTANTS

Safe Work and Environments Pty Ltd  
7/103 Majors Bay Road, Concord, NSW 2137

Client Project Name / Site etc (ie report title):

700 Bourke Street, Docklands VIC

Quote No.:

Date results required:

Std

Note: Inform lab in advance if urgent turnaround is required - surcharges apply

Lab Comments:

Tests Required

Comments

Asbestos

Type of sample

Date sampled

RiskTech Sample ID

Lab Sample ID

Gasket

30/11/2020

RTC2020-A01

Gasket

30/11/2020

RTC2020-A02

Insulation

30/11/2020

RTC2020-A03

0.35g

White

0.24g

Red

0.17g

Beige

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g

0.26g

0.17g