

Mirvac, 80 Pacific Highway, North Sydney, Air Shaft Report

Page 1 of 10



Client: Mirvac	Date: 040424	
Item: Air Shaft West side	Location: Level 13 West side	
Comment: Cat head scaffold inspection complete		
Inspector: JMR, TMN, ECN	Author: JMR	





Client: Mirvac

Date: 040424

Item: Air Shaft West side

Location: Level 13 West side

Comment: Top view of wall west 13, no change to condition

Inspector: JMR, TMN, ECN

Author: JMR



Client: Mirvac

Date: 040424

Time: AM

Item: Air Shaft West side

Location: Level 13 West side

Comment: Top view of wall west 12, no change to condition

Inspector: JMR, TMN, ECN

Author: JMR



Client: Mirvac

Date: 040424

Item: Air Shaft West side

Location: Level 13 West side

Comment: View of wall west 12, no change to condition. Spirit level showing bellying of 12mm

Inspector: JMR, TMN, ECN

Author: JMR



Client: Mirvac	Date: 040424	
Item: Air Shaft West side	Location: Level 13 West side	
Comment: Top of wall 12, misalignment from floor slab of 12mm		
Inspector: JMR, TMN, ECN	Author: JMR	



Client: Mirvac	Date: 040424	
Item: Air Shaft West side	Location: Level 13 West side	
Comment: Bottom view of wall 12 showing bellying		
Inspector: JMR, TMN, ECN	Author: JMR	



Client: Mirvac

Date: 040424

Item: Air Shaft West side

Location: Level 13 West side

Comment: Wall west 6 showing misalignment between slab and wall

Inspector: JMR, TMN, ECN

Author: JMR



Client: Mirvac

Date: 040424

Item: Air Shaft West side

Location: Level 13 West side

Comment: Same as above

Inspector: JMR, TMN, ECN

Author: JMR



Client: Mirvac

Date: 040424

Item: Air Shaft West side

Location: Level 13 West side

Comment: View of wall west 6, no change to condition

Inspector: JMR, TMN, ECN

Author: JMR



Client: Mirvac

Date: 040424

Item: Air Shaft West side

Location: Level 13 West side

Comment: View of wall west 2, no change to condition

Inspector: JMR, TMN, ECN

Author: JMR